

## DCTools Version 1.11.3

Last Updated	19 August 2010
Applicable products	DCTools
Audience	Eaton DC Channel Partners and Integrators
Related documents	
For more information	Contact: <a href="mailto:CustomerServiceNZ@eaton.com">CustomerServiceNZ@eaton.com</a> , or Simon Sloane, Product Manager. <a href="mailto:SimonSloane@eaton.com">SimonSloane@eaton.com</a>

### Description

DCTools Version 1.11.3 is a maintenance release.

DCTools will now run in Windows 7 (64 bit or 32 bit operating systems).

### Change History

- Version 1.11.3
  - Change default file type for datalog downloads to .csv
  - Turn off comm1 and comm2 in default settings.
- Version 1.11.2:
  - Support Windows 7
  - Support added for SC100 version 2
  - Support added for SC200 version 3.10
- Version 1.10.0:
  - Support added for SC200 Version 3.04
  - Improved hover text to show more specific help on selection lists.
- Version 1.9.16:
  - Support added for SC200 Version 2.61
- Version 1.9.13:
  - Rearranged some items for consistency with the Web view.
  - Updated the Help text.
  - Support added for SM65 Version 4.08
  - Support added for SC200 Version 2.57
  - Minor menu improvements
  - Added *Reset Battery Test Fail Alarm* button on *Battery Test* page.
- Version 1.9.9:
  - Support added for SM45-00C

## **Products supported**

DCTools Version 1.11.3 supports the following products:

- SC200 System Controller Version 1.20, 2.61 and earlier, 3.04 to 3.10
- SM45/SM65 Supervisory Modules Version 6.12 and earlier
- SM40/SM60 Supervisory Modules Version 4.08 and earlier
- SM50 Supervisory Module Version 5.05 and earlier
- SM30 Supervisory Module Version 2.10 and earlier
- CellSure battery Controller (CBC) Version 1.05 and earlier
- SM20 Supervisory Module Version 2.19 and earlier
- NSM35 Supervisory Module Version 1.1.5 and earlier
- SM45-00C Supervisory Module Version 1.06 and earlier